

Welding (Mig and/or Arc)

This course is suitable for anyone who is using Welders in the workplace to make sure that they are being operated correctly and safely.

One Day Training

09.30 – 16.30 approx.

The course covers...

- Personal Protective Equipment (PPE)
- Welder safety and settings. (Arc and/or Mig)
- Inspection, Handling, Transportation and Storage
- Safe use of Welder including Butt, Lap and Fillet welds

Venue

At your place of work

Equipment

Course requirements are listed on the next page for courses taken on your site.

Pre- Requisites

None



Park Hill Training & Assessment Centre

Park Farm, Park Hill Lane, Seagrave, Loughborough, LE12 7NG

T: 01509 815534

F: 0345 5578 498

www.parkhilltraining.co.uk

info@parkhilltraining.co.uk

Welding (Mig and/or Arc)

Venue Requirements (if course is at your site)

Room/ Area Required

- For theory sessions: dry, clean and well-lit workshop, heated if necessary.
- Washroom and toilet facilities.
- First Aid Equipment.
- Fire Extinguisher.

Equipment Required

- 1 Welder between 2 trainees (Mig and or Arc)
- Shielding Gas for Mig welder – if Mig being used
- Arc welding electrodes (rods) / MIG wire
- Operator manual.
- Equipment must comply with PUWER Provision and Use of Work Equipment Regulations and the Electricity at Work Regulations.
- An appropriate toolkit for which ever machine is being used for training.
- Plenty of clean steel off cuts of different thicknesses
- PPE for all Trainees
 - Welding helmet
 - Steel toe-capped work boots
 - Safety glasses
 - Ear defenders
 - Gauntlets
 - Cotton rich or fire resistant overalls
 - Fume protection eg. Air fed Welding Helmet or Local Exhaust Ventilation unit

Other Requirements

- Upon arrival on site the instructor may postpone the training or assessment if the equipment or site are unsuitable. Payment will still be due and there will be an extra cost for the rescheduled day.
- All trainees must be fit enough for the training or assessment.



Park Hill Training & Assessment Centre

Park Farm, Park Hill Lane, Seagrave, Loughborough, LE12 7NG

T: 01509 815534

F: 0345 5578 498

www.parkhilltraining.co.uk

info@parkhilltraining.co.uk